

ExxonMobil
Refining & Supply Company
Global Remediation

4096 Piedmont Avenue #194
Oakland, California 94611
510.547.8196
510.547.8706 Fax
jennifer.c.sedlachek@exxonmobil.com

Jennifer C. Sedlachek
Project Manager

ExxonMobil
Refining & Supply

November 29, 2005

Mr. Chris Murray
Subregional Water Management System
Industrial Waste Section
4300 Llano Road
Santa Rosa, California 95407


RE: Former Exxon RAS #7-3035/4501 Sonoma Highway, Santa Rosa, California.

Dear Mr. Murray:

Attached for your review and comment is a copy of the letter report entitled *Quarterly Self-Monitoring Report*, dated November 28, 2005, for the above-referenced site. The report was prepared by Environmental Resolutions, Inc. (ERI) of Petaluma, California, and details remedial activities for the subject site.

If you have any questions or comments, please contact me at 510.547.8196.

Sincerely,




Jennifer C. Sedlachek
Project Manager

Attachment: ERI's Quarterly Self-Monitoring Report, dated November 28, 2005.

cc: w/ attachment
Ms. Jo Bentz, California Regional Water Quality Control Board, North Coast Region

w/o attachment
Ms. Paula Sime, Environmental Resolutions, Inc.



ENVIRONMENTAL RESOLUTIONS, INC.

November 28, 2005
ERI 200311CM.L72

Ms. Jennifer C. Sedlachek
ExxonMobil Refining & Supply – Global Remediation
4096 Piedmont Avenue #194
Oakland, California 94611

SUBJECT Quarterly Self-Monitoring Report
Former Exxon Service Station 7-3035
4501 Sonoma Highway, Santa Rosa, California

City of Santa Rosa Industrial User Permit No. SR-GW6100

Ms. Sedlachek:

At the request of Exxon Mobil Corporation (Exxon Mobil), Environmental Resolutions, Inc. (ERI) is submitting this Quarterly Self Monitoring Report documenting the operational status of the groundwater extraction and treatment (GET) system at the subject site during the fourth quarter 2005. ERI is submitting this report in compliance with the requirements of the discharge permit set forth by the Santa Rosa Subregional Wastewater Management System (the City).

The GET system did not operate during the fourth quarter 2005. The system was shut down on August 25, 2005, for repairs to the two rotary vane extraction blowers. ERI restarted the system on September 1, 2005, to troubleshoot the rotary vane blowers. Approximately 37 gallons of water were discharged during troubleshooting activities. ERI subsequently shut down the system pending redesign.

The system did not operate during the reporting period; therefore, samples were not collected and associated laboratory analytical results and Critical Parameters Report forms are not included in this submittal.

DOCUMENT DISTRIBUTION

ERI recommends forwarding a copy of this report to:

Mr. Chris Murray
Subregional Water Management System
Industrial Waste Section
4300 Llano Road
Santa Rosa, California 95407


Ms. Jo Bentz
California Regional Water Quality Control Board
North Coast Region
5550 Skylane Boulevard, Suite A
Santa Rosa, California 95403

November 28, 2005

Please contact Ms. Paula Sime, ERI's project manager for this site, at (707) 766-2000 with any questions regarding this submittal.

Sincerely,
Environmental Resolutions, Inc.

SCANNED
IMAGE
Cory A. Weigman
Senior Staff Engineer


Paula Sime
Project Manager